From: ANDERSON Jim M

To: (b) (6) pdxharborcag@lists.onenw.org

Cc: Marcia.Danab@state.or.us; GAINER Tom; Kristine Koch/R10/USEPA/US@EPA

Subject: RE: [pdxharborcag] Proposed Source Control Action at BP/Arco

**Date:** 01/09/2007 11:11 AM

#### Jeanne,

Sure, 2/28 works well.

James M. Anderson

**DEQ Northwest Region** 

Portland Harbor Section

Phone (503) 229-6825

Fax (503) 229-6899

-----Original Message-----

From: (b) (6)

Sent: Tuesday, January 09, 2007 11:03 AM

**To:** ANDERSON Jim M; pdxharborcag@lists.onenw.org

**Cc:** Marcia.Danab@state.or.us; GAINER Tom; koch.kristine@epa.gov **Subject:** Re: [pdxharborcag] Proposed Source Control Action at BP/Arco

Hi, Jim,

Is Feb. 28th early enough? Does it work for you? Note it is not our usual meeting time.

Jeanne

In a message dated 1/5/2007 2:16:54 PM Pacific Standard Time, ANDERSON.Jim@deq.state.or.us writes:

Happy New Year, everyone!

I understand you have very full agendas for the next several PH CAG meeting, but I'd like to take several minutes in one of the next upcoming CAG meetings to discuss BP's source control proposal below.

# 

The purpose of this e-mail is to give you all a head's-up that Arco/BP (BP) recently proposed to DEQ &EPA an extensive source control action at their facility.

# **Site Description**

The 14-acre subject site (Terminal 22T) is located at 9930 W St. Helens Road, Portland, Oregon, on the west bank of the Willamette River at approximately river mile 4.9 in the Portland Harbor. It was originally developed as a bulk petroleum terminal in 1932 and currently consists of 27 above ground storage tanks, a truck loading rack, and several

buildings and warehouses.

Historical releases of petroleum product (sources unknown, but likely include the truck loading rack) and a diesel product pipeline leak in 1991 between the northern tank farm and the truck loading rack. Such releases have resulted in an accumulation of liquid phase hydrocarbons (LPH) consisting of relatively weathered and un-weathered diesel product that floats on groundwater.

### **Existing Source Control Measures**

An 800-foot concrete seawall was installed along the entire frontage adjacent to the Willamette River in the 1940's, and it extends down to approximately 1.6 feet msl. A storm water collection system and two oil/water separators were installed in 1968, and additional storm drainage systems and four interceptor wells on the landward side of the seawall were installed in 1971. Two additional interceptor wells were constructed in 1994. Product skimmers operated in the six interceptor wells. Extracted product and groundwater are treated in an on site oil/water separator and carbon unit and discharged to the river under an NPDES permit. Between 1997 and 2003, about 7,800 gallons/year of petroleum product have been recovered from the subsurface. Recovery rates improved using new wells and mobile pumping systems: about 13,000 gallons of product were recovered in 2003. Product recovery has also been conducted from two wells located between the seawall and the truck loading rack.

In 2003 BP proposed to DEQ &EPA, replacing and enhancing their existing hydraulic containment system (i.e., pump and treat) at their Terminal 22T site. The existing seawall and groundwater/light non-aqueous phase liquid (LNAPL) pumping system is largely effective in containing liquid phase petroleum product from upland historic releases, but periodic, relatively small volumes of contaminated groundwater/LNAPL have by-passed the control &have been released to the river under certain hydrologic conditions. In 2004 BP enhanced their existing hydraulic containment system with the installation of a number of new extraction wells. The enhanced source control efforts have been effectively operating since early-2005.

#### **Proposal**

BP recently advised us that the existing concrete seawall/revetment (which was installed years ago for geotech/stability reasons, not source control) is failing; needs to be removed; &a new seawall needs to be constructed. BP proposed that a sheetpile wall be installed along their entire shoreline for slope stability. This proposed sheetpile wall would act as the new seawall. BP proposed to do a riverward sediment removal during the demolition of the existing seawall/revetment, if the extent of contaminated sediment was limited to the beach &near shore area (i.e., sediment contamination did not extend beyond the nearshore very far into the river). BP completed an in-water, sediment investigation in summer '06 to determine the extent of sediment contamination. BP says the results indicate that total petroleum hydrocarbon (TPH) contamination in sediment is largely restricted to the nearshore area.

The basics of BP's proposal are:

- -Installation of new sheet pile wall to ensure slope stability (spring/summer '07)
- -Removal of old concrete seawall and revetment (summer/fall '07)
- -Removal of 16,000cy of beach and near-shore soil/sediment (summer/fall '07)

During a 12/7/06 BP/DEQ/EPA meeting to discuss BP's most recent source control proposal, BP submitted their 12/06 "Basis of Design (BOD) Report- Revetment Source Control Measure" to DEQ and EPA. DEQ and EPA are currently reviewing BP's BOD report.

#### **DEQ/EPA** roles

DEQ and EPA agreed that if the in-water contamination was restricted to the nearshore area that BP's proposal could be completed under DEQ's source control oversight rather than

splitting the project into an upland source control and in-water early action. Both EPA and DEQ are currently reviewing the BOD Report to determine if both agencies agree with BP's conclusion that contamination riverward of the seawall is restricted to the near-shore area. Kristine Koch will be EPA's lead on the project.

# **Next Steps**

BP has a very ambitious project schedule and wants to start construction this year. DEQ and EPA will review BP's 12/06 BOP Report and advise BP whether we can support their proposal. If both agencies agree to BP's proposal, DEQ will issue a draft Source Control Decision in late-winter or early-spring 2007, and request comments from our state, federal, and tribal partners at that time. We will also alert and request review/comments from the Portland Harbor Community Advisory Group and public.

Please contact me or DEQ's BP project Project Manager, Tom Gainer (503.229.5326), with any questions or concerns.

James M. Anderson DEQ Northwest Region Portland Harbor Section Phone (503) 229-6825 Fax (503) 229-6899

Jeanne Longley

(b) (6)